

Nº 11540

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/27/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 242'

HOUSE NO. 1275

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Steve Miller Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to scale

SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11540

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 11, 2007

RECEIVED OF _____ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED S. Miller Excavating

REPAIR TO TAP Tap Sanitary SEWER ON THE West S
CUTOFF

OF Lanedale Street AVE. ST. TYPE OF STREET Concrete

THE PREMISES BEING LOT NO. 1617, HOUSE NO. 127

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Steve Miller Excavating

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.