

Nº 11543

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7/3/02 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 144'
HOUSE NO. 801
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Miracle Plumbing
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Installed Cleanout out side of House. See permit # 6793.

Not to scale

SIGNED *MAH* in *K* FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

N^o 11543

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/2, 2021

RECEIVED OF Miracle Plumbing FEE OF \$ 122

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Sanitary SEWER ON THE South S
CUTOFF

OF Leggett Ave 47th AVE
ST. TYPE OF STREET Leggett

THE PREMISES BEING LOT NO. 11358, HOUSE NO. 801

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Miracle Plumbing

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**