FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/9/02 HOUSE NO. 1100 SIZE OF PIPE USED 6" WAS LATERAL AT CURB? YES	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTORLeon_Glick
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.
Not to scole	27: Curb Lanedale 18'
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE

N° 11545

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,	<u></u>
RECEIVED OF Stull Miller Extractor of \$ -	<u>5</u> 7
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON THE SEWER ON THE OF STREET	{
THE PREMISES BEING LOT NO. 100/3 , HOUSE NO. 1/00	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES DEPARTMENT OF PUBLIC SERVICE.	OF THE
NAME OF CONTRACTOR SUM	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.