## Nº 11546

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 7/10/02  HOUSE NO. 1035  SIZE OF PIPE USED 6"  WAS LATERAL AT CURB? yes | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
|--|---|
| WAS ATTACHED TO MAIN   | NAME OF CONTRACTORHumbert   |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF E                                       | BUILDING SERVED.  |
|  | 8.5'dp/18'0 Curb  Repaired 45" of Lateral   |
| Not to scale   |   |
|  |   |
| SIGNED Inspector for City  | FILED AT ENGINEER'S OFFICE  |

## Nº 11546

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

|   | MASSILLON, OHIO,                              | 7/20        |
|---|---|-------------|
| RECEIVED OF HOLLANDER CONTROL                       | FEE OF \$                                     |             |
| FOR WHICH PERMISSION IS GRANTED                     |   |             |
|   | VER ON THE                                    | NHWANIA     |
| CUTOFF AVE.   | PÉ OF STREET                                  | 1           |
| THE PREMISES BEING LOT NO.                          | , HOUSE NO                                    | 7.          |
|   |   |             |
| WORK TO BE DONE IN ACCORDANCE WITH OPDINANCE NO. 19 | .1971 DULY PASSED BY THE CITY COUNCIL, AND RU | JLES OF THE |
| DEPARTMENT OF PUBLIC SERVICE.                       |   |             |
| 7/ A.   | 1,-   |             |
| NAME OF CONTRACTOR                                  | Add Commence                                  |             |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.