FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10/18/02 HOUSE NO. 1308 SIZE OF PIPE USED 6"	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 162' DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Yes	•
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Grabil
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BI	UILDING SERVED. Tyler Mills Lone ME 1304 Tyler Mills Lone ME 22. 18' 7' 2' 18'
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
HEMARKS.	

Nº 11548

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI

PERMIT TO TAP SEWER

$\frac{1}{1}$
RECEIVED OF ALLIQUED AND SERVICED FEE OF \$ 5
TO TAP SEWER ON THE MALTA CUTOFF JULY MILL SEWER ON THE MALTA AVE. AV
THE PREMISES BEING LOT NO. 47 0 (857 , HOUSE NO. 430 8
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.