## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10/18/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	162'
HOUSE NO1324		
SIZE OF PIPE USED6"		
WAS LATERAL AT CURB? Yes		
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	Grabil
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.	1308
Not to scole	Z.>	Tyler Milis Lone NE  4'dp  1324  22'  45'45'  18'  18'
SIGNED Inspector for City	FILED AT ENGINEER	S'S OFFICE
REMARKS		

## Nº 11549

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	7/60 DUX FEE OF \$ .5
RECEIVED OFFOR WHICH PERMISSION IS GRANTED	June Corro	FEE OF \$
TO TAP CUTOFF LALL AND	SEWER ON THE	Moleth
THE PREMISES BEING LOT NO.	P1 0 C 857 , HOUSE NO.	1324
WORK TO BE DONE IN ACCORDANCE WIT DEPARTMENT OF PUBLIC SERVICE.	TH ORDINANCE NO. 19.1971 DULY PASSED BY THE (	CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	Graluel	and the same of th

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.