N° 11551

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	174'
HOUSE NO. 1344	THE PARTY OF THE P	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? Yes	OUTD LINE AND DEL TIT	φ
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	Grabil
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL	JILDING SERVED.	s' 5'
Nat la scole	.* .*	curb 9' 63' 22' 5 45' 45' 45' 45' 45' 45' 45' 45' 46' 1348 Tyler Mils Lone NE
SIGNED My My My Inspector for City	FILED AT ENGINEER'S (1354 1358 DFFICE
REMARKS		

Nº 11551

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI PERMIT TO TAP SEWER

// MASSILLON, OHIO, $\frac{7//\rho_{20}}{}$)
RECEIVED OF LOUIS GUILD CALLY FEE OF \$	50
FOR WHICH PERMISSION IS GRANTED	
REPAIR TO TAP CUTOFF CUTOFF	
OF	
THE PREMISES BEING LOT NO. 77 0 (857 , HOUSE NO. 1344)	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF TH DEPARTMENT OF PUBLIC SERVICE.	ίΕ
NAME OF CONTRACTOR	
A	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.