## Nº 11560

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9/12/02	IF SO, HOW AND LOCATION FROM	91'
HOUSE NO. 1424	FIRST WANNOLE DOWN STREAM	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		<del></del>
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Grabill 1428 1435
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	JILDING SERVED.	
Not to scole		45'4 22' 5'E 45' 1424 1434
SIGNED July inspector for City	FILED AT ENGINEER'S	OFFICE
REMARKS		manu II

Nº 11560

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,	7//20)	
RECEIVED OF ANDULUS CONTINUES	Child FEE OF S 3	Ĺ
FOR WHICH PERMISSION IS GRANTED		_
REPAIR TO TAP SEWER ON THE	MAUTH	. :
OF	Assila Col	
A Diggs	SE NO	
	,	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED B	Y THE CITY COUNCIL, AND RULES OF THE	
DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	<u>.                                    </u>	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.