N° 1156 $\bar{2}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED9/12/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	91'	
HOUSE NO. 1434	THAT WANTOLL DOWN STILLAN		
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			7
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Grabill 1428	1438
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.		
Nat to scole		45.4.1 45.4.22: 15.5.1 45.1424	143A
	G	91*	
SIGNED Why my ly	FILED AT ENGINEER'	S OFFICE	
luspector for City			
REMARKS			

Nº 11562

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

ρ .	MASŞILLON, OHIO,	17/100
RECEIVED OF Andrew Color	Coxho Chips	FEE OF \$
OR WHICH PERMISSION IS GRANTED		
	ERJON THE	uth
CUTOFF AVE.	OF STREET	adalt
THE PREMISES BEING LOT NO.	857 , HOUSE NO.	1434
		•
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.	1971 DULY PASSED BY THE CITY COUN	ICIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.		
IAME OF CONTRACTOR		•
17		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.