

Nº 11569

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/26/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 122'

HOUSE NO. 1468

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11569

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/1/68
RECEIVED OF Springhill Condo Corp. FEE OF \$ 15.00

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP 2 Sanitary SEWER ON THE NORTH S
CUTOFF

OF Tylers Mill Ave. ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. PT 02857, HOUSE NO. 1468

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Qualice

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.