

Nº 11570

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7/26/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 122'

HOUSE NO. 1474

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Jeffrey M. King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11570

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/11/61
RECEIVED OF Springfield Cattle Co. FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP Sanitary SEWER ON THE NORTH SIDE
CUTOFF Tyler's Mill Rd AVE. 796
OF 796 ST. TYPE OF STREET Residential
THE PREMISES BEING LOT NO. PL 06 857, HOUSE NO. 1434

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Michael

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.