

Nº 11575

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/18/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 136'

HOUSE NO. 1498

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to scale

SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11575

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/1 2011
RECEIVED OF Springfield Cnty. Eng. FEE OF \$ 1.00

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP 2 Structural SEWER ON THE main SII
CUTOFF

OF Ida M. Miller Ave ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. P1 06 857, HOUSE NO. 1490

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Gardner

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.