

Nº 11582

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/8/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM Tapped into MH

HOUSE NO. 2832

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

*[Signature]*

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11582

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 7/1/52

RECEIVED OF Halderbaum

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR  
TO TAP  
CUTOFF

Sanitary  
17th St SW

SEWER ON THE

East

SI

OF

AVE.

ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO. 01931

, HOUSE NO. 2832

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Halderbaum

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**