FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9/4/02 HOUSE NO. 1.330 SIZE OF PIPE USED 6"	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM Topped into mh DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?yes	• ·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Holderbaum
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF E	BUILDING SERVED. 1330 13TH ST SE 45° 2'dp 8'-45° 8'-67' Topped into MH
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
DEMADIC	

Nº 11590

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO	,	7/200
RECEIVED OF	m Sewer and I	lan FEE OF S	, 50
FOR WHICH PERMISSION IS GRANTED	Cyne		
TO TAP CUTOFF	SEWER ON THE	east	S
	AVE. ST. TYPE OF STREET		
THE PREMISES BEING LOT NO.	543H	JSE NO. 133	<u> </u>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	CE NO. 19.1971 DULY PASSED B	BY THE CITY COUNCIL, AND F	RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.			4
NAME OF CONTRACTOR Hudar Va	Um	<u></u>	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

Fermit to repair lateral only-rot to tap main trunk.