Nº 11599

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM _ DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	87'
WAS LATERAL AT CURB? Yes  WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	_Annihilation_Wrecking
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.	-
iot to scole		144/145 Oak Ave SE 19 <sup>1</sup>
		O 87' Dak Ave St
SIGNED 311 Pappa 5 Inspector for City	FILED AT ENGINE	EER'S OFFICE
REMARKS		

## Nº 11599

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		MASSILLON, OHIO		8/0/07/20
RECEIVED OF	Analitation	Wrecking		FEE OF \$ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
OR WHICH PERMISSION IS GRANTED				
THE PREMISES BEING LOT NO.	SEWE AVE. ST. TYPE	. 0. 0	6139	Missi I
VORK TO BE DONE IN ACCORDANCE V DEPARTMENT OF PUBLIC SERVICE.	VITH ORDINANCE NO. 19.1	971 DULY PASSED	BY THE CITY COUN	ICIL, AND RULES OF THE
IAME OF CONTRACTOR	Aintholion		· · · · · · · · · · · · · · · · · · ·	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.