Nº 11600

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED8/12/02 | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 63' |
|---|---|
| HOUSE NO. 1030 | THE PARTICLE DOWN OF HAME |
| SIZE OF PIPE USED6" | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB?Yes | |
| WAS ATTACHED TO MAIN Yes | NAME OF CONTRACTOR |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL | 1 |
| Not to scule | 45° -4'-1 45° -4'-1 45° -4'-1 45° -4'-1 45° -4'-1 |
| | 63' |
| SIGNED BITT Pappas Inspector for City | FILED AT ENGINEER'S OFFICE |
| REMARKS | |

Nº 11600

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| • | | _ / |
|--------------------------------------|---|-----------------------------|
| \wedge | MASSILLON, OHIO, | <u> </u> |
| RECEIVED OF | there Excavatry | FEE OF \$ |
| / | <i>O</i> • | |
| FOR WHICH PERMISSION IS GRANTED/ | | |
| REPAIR TO TAP | SEWER ON THE | Cast |
| OF 3) Mily | AVE. ST. TYPE OF STREET | andalt- |
| THE PREMISES BEING LOT NO. | $\frac{147.6}{}$, House no. $\underline{}$ | 1030 |
| | , | , 0 - |
| WORK TO BE DONE IN ACCORDANCE WITH (| DRDINANCE NO. 19.1971 DULY PASSED BY THE CITY | Y COUNCIL. AND RULES OF THE |
| DEPARTMENT OF PUBLIC SERVICE. | | |
| . / | A | |
| NAME OF CONTRACTOR | LICI. | <i>*</i> |
| | | • |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.