Nº 11602

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED <u>8/12/02</u>	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 110'	
HOUSE NO249		
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Holderboum	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	UILDING SERVED. 45'2'	
Not to scole	-43'	
	6-1 10'dp curb	ノ
	110' 25th NW	—
SIGNED Jeffy on My Mospector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 11602

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLOI	IN, OHIO,/	/ ♦, 20
RECEIVED OF	Holderbau	FEE OF \$	_5
FOR WHICH PERMISSION IS GRANTED			
REPAIR TO TAP CUTOFF 1 th 1.	SEWER ON THE _		5
OF	AVE. ST. TYPE OF STREET		
THE PREMISES BEING LOT NO	/3223	, HOUSE NO	9
			/
WORK TO BE DONE IN ACCORDANCE W	ITH ORDJNANCE NO. 19.1971 DULY PA	ASSED BY THE CITY COUNCIL, AND FIULES C	OF THE
DEPARTMENT OF PUBLIC SERVICE.	/		
NAME OF CONTRACTOR	Malufat		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.