

Nº 11608

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 10/01/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

80'

HOUSE NO. 1855

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Bontrager

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11608

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/22

RECEIVED OF Bontingen FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sanitary SEWER ON THE West SIDE
CUTOFF Chas. Webster Ave. AVE. Asphalt
OF _____ ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. 15970, HOUSE NO. 1855

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Efficient Homes

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.