

N<sup>o</sup> 11610

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED 8/29/02

IF SO, HOW AND LOCATION FROM

HOUSE NO. 4595

FIRST MANHOLE DOWN STREAM 120'

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR John's Exc

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11610

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

# PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/29/2007

RECEIVED OF

*John's Excavating*

FEE OF \$

*57*

FOR WHICH PERMISSION IS GRANTED

REPAIR  
TO TAP  
CUTOFF

*Sanitary*  
*Brightley Ave*

SEWER ON THE

*South*

SI

OF

AVE

ST. TYPE OF STREET

*Residential*

THE PREMISES BEING LOT NO.

*116140*

HOUSE NO.

*4595*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Blair Homes*

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**