

Nº 11611

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 9/5/02

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

71'

HOUSE NO. 2575

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

*[Signature]*

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N<sup>o</sup> 11611

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

# PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/14, 20

RECEIVED OF

*Melanite*

FEE OF \$

57

FOR WHICH PERMISSION IS GRANTED

REPAIR  
TO TAP  
CUTOFF

SEWER ON THE

SI

OF

AVE.  
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Harvey Ashley*

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**