Nº 11613

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9/9/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	110"	
HOUSE NO	FIRST MANNOLE DOWN STREAM	110	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?Yes			
WAS ATTACHED TO MAINYes	NAME OF CONTRACTOR	H&W	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.	1500 181	мt 5'+ 22°
		N	100-
at to scole			, , ,
			5 ¹ 45*
			- 3, ^{q‡}
2/2			
SIGNED BILL TAPONS Inspector for City	FILED AT ENGINEER'S	S OFFICE	
•			
REMARKS			

Nº 11613

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	f A	MASSILLON,	OHIO,	91	28
RECEIVED OF	7/10)			FEE OF \$	
FOR WHICH PERMISSION IS GRANTED .	•				
REPAIR TO TAP CUTOFF OF THE PREMISES BEING LOT NO.	7160 S	SEWER ON THE VE. IT. TYPE OF STREET _	, HOUSE NO.	1600	
WORK TO BE DONE IN ACCORDANCE W	/ITH ORDINANCE I	NO. 19.1971 DULY PAS	SED BY THE CITY COU	NCIL, AND RULES O	FTHE
DEPARTMENT OF PUBLIC SERVICE.	/ 💉				
NAME OF CONTRACTOR	**/**********************************				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.