

Nº 11624

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED:

DATE INSPECTED 10/14/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 796-798

SIZE OF PIPE USED 2" force main

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH ---

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Malovite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11624

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

9/30

RECEIVED OF _____

Malawite

FEE OF \$ _____

57

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE _____

East

SI

OF _____

27th St

AVE.

TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

16021

HOUSE NO. _____

796-198

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Malawite

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**