

Nº 11636

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10/18/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 48' from upstream

HOUSE NO. 2385

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's Excavating

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Bill Pappas FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11636

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/23

RECEIVED OF

Jersey's Excavating

FEE OF \$

10.57

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Sanitary
Wingate State Ave.

SEWER ON THE

West

S

OF

AVE.
TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

15920

HOUSE NO.

2385

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Star

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**

Nº 11637

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10/27/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 210'

HOUSE NO. 2390

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Jerry's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS