

Nº 11639

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 12/27/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM.

HOUSE NO. 817

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR American Demo

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral was cut -off and capped. No measurements.

Not to scale

SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11639

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/23

RECEIVED OF

American Demolition

RECEIVED

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE

OF

AVE

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

15031

HOUSE NO.

817

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

American Demolition

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**