

Nº 11649

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

See Permit # 11671

SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11649

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/11, 2015

RECEIVED OF Bontlinger FEE OF \$ 52

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sp. Sanitary SEWER ON THE North SIDE
CUTOFF Indefinite AVE.

OF Indefinite ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 01960, HOUSE NO. 1385

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bontlinger

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.