

Nº 11650

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11/25/02

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM Topped into Mh

HOUSE NO. 2395

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Molovite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED *Jeffrey M. [Signature]* FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11650

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11-22, 20

RECEIVED OF Malavite Malavite FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sanitary SEWER ON THE South S

OF Urban AVE. Asphalt
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 16231, HOUSE NO. 2395

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.