Nº 11651

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 12/12/02 HOUSE NO. 2430 SIZE OF PIPE USED 6" WAS LATERAL AT CURB? Yes | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM ? DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
|---|---|
| WAS ATTACHED TO MAIN <u>Yes</u> SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B | NAME OF CONTRACTOR ———————————————————————————————————— |
| SIGNED BILL PAPERS In Spector for City | 45° 10' FILED AT ENGINEER'S OFFICE |

Nº 11651

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | \cap | MASSILLO | N, OHIO, | :. | 11/201 |
|---------------------------------|------------------|-----------------------|---------------------|-----------------|------------|
| RECEIVED OF | Jury | Ja Cu | Caustul | FEE OF S | 5 |
| FOR WHICH PERMISSION IS GRANTE | 6 / | <u> </u> | | <u> </u> | |
| REPAIR TO TAP | Aury | SEWER ON THE | | 1 | |
| of Wheat | trate & | AVE OF STREET | · | 12 11 Kg 1 | 4 |
| /) THE PREMISES BEING LÖT NO | | 603/ | , HOUSE NO | 1 24 | 30 |
| WORK TO BE DONE IN ACCORDANCE | E WITH ORDINANCE | E NO. 19.1971 DULY PA | ASSED BY THE CITY (| COUNCIL, AND RU | LES OF THE |
| DEPARTMENT OF PUBLIC SERVICE. | Da. 1 | 1 1 | | \$ * | |
| NAME OF CONTRACTOR | Marie M. | 7 6-1 | | | |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.