

N^o 11670

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/9/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM ?

HOUSE NO. 1314

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Miracle Plumbing

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED _____

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11670

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

117²⁰

RECEIVED OF _____

Myra's Plumbing

FEE OF \$ _____

125

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

7' Sewer

SEWER ON THE _____

SI

OF _____

Angela Ave

AVE

ST. TYPE OF STREET _____

Angela Ave

THE PREMISES BEING LOT NO. _____

12678

HOUSE NO. _____

1314

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Myra's Plumbing

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.