

N^o 11675

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/4/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 212'

HOUSE NO. 1224

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED [Signature] FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11675

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/3

RECEIVED OF

Holderbaum

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE

East

SI

OF

13th St SW

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

8888

HOUSE NO.

1224

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Holderbaum

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

Nº 11676

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/4/03

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM Topped into MH

HOUSE NO. 2240

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT

WAS LATERAL AT CURB? Yes


CURB LINE AND DEPTH

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS