

Nº 11676

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/4/03

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM Topped into MH

HOUSE NO. 2240

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 11676

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/3 20

RECEIVED OF

Malawite

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Sanitary
Boulenger Green Dr

SEWER ON THE

East

SII

OF

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

16252

, HOUSE NO.

2240

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Smith

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.