

Nº 11683

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/14/03

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 110'

HOUSE NO. 2455

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's Exc

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11683

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March, 13, 2020

RECEIVED OF Jerry's Excavating FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sanitary SEWER ON THE west SIDE
CUTOFF OF wright state dr AVE ST TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15919, HOUSE NO. 2455

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Jerry's Excavating

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.