

Nº 11687

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 1291

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____ FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11687

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/12/20

RECEIVED OF Tuesat

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP _____ SEWER ON THE _____ SI
CUTOFF 8th St
OF 14th St AVE. ST. TYPE OF STREET Asphalt
THE PREMISES BEING LOT NO. 16529, HOUSE NO. 1191

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Roseman

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.