

Nº 11692

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED \_\_\_\_\_

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. \_\_\_\_\_

SIZE OF PIPE USED \_\_\_\_\_

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_

NAME OF CONTRACTOR \_\_\_\_\_

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED \_\_\_\_\_

Inspector for City

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

Nº 11692

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 03/21/03, 2003

RECEIVED OF \_\_\_\_\_ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED John's excavating

REPAIR TO TAP tap sandail SEWER ON THE South SI  
CUTOFF

OF Evangel Ave NW AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16145, HOUSE NO. 4573/4575

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR John's Excavating

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**