

Nº 11696

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/25/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2811

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

R.P. Construction

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11696

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 03/25/03

RECEIVED OF _____ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED RP Construction

REPAIR
TO TAP for sanitary SEWER ON THE south SI
CUTOFF

OF Turning Leaf Ave AVE
ST/TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16114, HOUSE NO. 2811

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR RP Construction

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**