Nº 11701

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED4/11/03	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	21'
HOUSE NO		
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?Yes		
WAS ATTACHED TO MAINYes	NAME OF CONTRACTORMali	vite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BI	JILDING SERVED.	365 Show NE
Not to scale	† '	
		6'- ^{8'dp} 22°
		sewer main runs through yard 21'
	-	curb
		Show NE
signed July in thy	FILED AT ENGINEER'S O	
Inspector for City		
		·
REMARKS		

Nº 11701

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO, 4/, 20
RECEIVED OF 77/12 Lacute	
FOR WHICH PERMISSION IS GRANTED	and Cuchon Hower
REPAIR TO TAP SEWE	R ON THE
CUTOFF AVE. ST. TYPE	OF STREET Dept. 1. 1
THE PREMISES BEING LOT NO.	77 , HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1	971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR MALLILLE	to an arms

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.