Nº 11709

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-28-03 HOUSE NO. 2/50	IF SO, HOW AND LOCATION FROM 35 '	
SIZE OF PIPE USED 6"  WAS LATERAL AT CURB? 75	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Malavite	LILLIAN SERVICE STREET
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.	2150 Augusta DR SE
SIGNED Bill Pappas Inspector for City	FILED AT ENGINEER'S OFFICE	-7'

REMARKS \_\_\_\_\_

## Nº 11709

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, C	OHIO,	04/25/03	
RECEIVED OF			FEE OF \$	
	Malavite	وريد من واستند	nt or	
FOR WHICH PERMISSION IS GRANTED	/- Jaiaviii	LALAVA	<u> </u>	
TO TAP TO SONITARY	SEWER ON THE		Feet	
OF AUGUSTA DIVE	AVE. ST. TYPE OF STREET		CONCRETE	
THE PREMISES BEING LOT NO.				
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR	Malavite			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.