


Nº 11716

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/1/03 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM To tap into MH
HOUSE NO. 614
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? Yes
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Quality Exc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED *Jeffrey M. King* Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11716

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/20

RECEIVED OF

Quality Excavating

FEE OF \$

57

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE

SI

OF

AVE.)

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.


NAME OF CONTRACTOR

Quality

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**

330-495-8654 CELL
492-9340 OFF

492-9340 Off



219

614

Q. 70
From 1856
to 1864.

[illegible][illegible]

כסא קדוש

26, 27, 28

26.

Case 2116

五

47

75

921

—

220

Второй

五