## Nº 11722

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED5/13/03	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?Yes		
WAS ATTACHED TO MAINYes	NAME OF CONTRACTORK_Glick	553. Washington
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF E	BUILDING SERVED.	
		8'dp
Not to Scale	<del>Z-&gt;</del>	
		\-46'
•		<u> </u> 12'dp
SIGNED BIT Pappas	FILED AT ENGINEER'S OFFICE	
Inspector for City		
REMARKS		

## Nº 11722

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF RECEIVED OF	MASSILLON, OHIO,FEE OF \$	5/.26_ 5Z
OR WHICH PERMISSION IS GRANTED	•	
On WHICH PERIVISSION IS SHANTED		
REPAIR	RONTHE (ALC. 5)	
O TAP SHWEF	R ON THE	S
OF AVE.	OF STREET AGALAST	
N N	7, HOUSE NO	
THE I THEIVIGEO BEING LOT IVO.	, HOUSE NO.	· =+
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.19	971 DULY PASSED BY THE CITY COUNCIL, AND RU	LES OF THE
EPARTMENT OF PUBLIC SERVICE.		
IAME OF CONTRACTOR		_
$-\Lambda$	1 mg 1 mg 1	

Note: This permit cover's work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.