FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5/28/03 HOUSE NO. 2405 SIZE OF PIPE USED 6" WAS LATERAL AT CURB? Yes	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 12' from up srtream DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR H&W 364
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED. 34'- 20' 22' 22' 22' 3'dp 27'- 12' 0
SIGNED Jeffy III Mig Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

N^{0} $1\dot{1}7\ddot{3}2$

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,	
RECEIVED OF HOW Contractors of FEE	EOF\$
FOR WHICH PERMISSION IS GRANTED ON LO DEILLING	
O TAP SEWER ON THE WEST	·
OF BUSTIC BUD SWET TYPE OF STREET	
THE PREMISES BEING LOT NO. <u>61.512</u> , HOUSE NO. <u>2</u>	405
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR HOT WE CONTROCTORS	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.