

Nº 11739

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 6/11/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM --

HOUSE NO. 611

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale

SIGNED



Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11739

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 06/05/03

RECEIVED OF

Glen Tissot

FEE OF \$

11

FOR WHICH PERMISSION IS GRANTED

Tissot Excavating

REPAIR

TO TAP

CUTOFF

tap sanitary

SEWER ON THE

West

SI

OF

Erie Street South

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

06 47

, HOUSE NO.

06 47 611

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Tissot

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

