

Nº 11740

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/23/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 2370

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH ---

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED Bill Rappas

Inspector for City

FILED AT ENGINEER'S OFFICE ---

REMARKS ---

Nº 11740

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

06/06/03

RECEIVED OF

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Jerry's Excavating

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE

East

SI

OF

Wright State Dr SE

AVE

ST TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

15932

, HOUSE NO.

2370

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Jerry's

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

Nº 11741

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/23/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 2380

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH ---


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE ---

REMARKS ---