

Nº 11742

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/9/03

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM 13'

HOUSE NO. 360

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED

Bill Peppers

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11742

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, \_\_\_\_\_

06/09/03

20

RECEIVED OF \_\_\_\_\_

FEE OF \$ \_\_\_\_\_

50

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

Jerry's Excavating

REPAIR  
TO TAP  
CUTOFF

tap sanitary

SEWER ON THE \_\_\_\_\_

East

SI

OF \_\_\_\_\_

Joshua Street NW AVE.

ST. TYPE OF STREET \_\_\_\_\_

asphalt

THE PREMISES BEING LOT NO. \_\_\_\_\_

16445

, HOUSE NO. \_\_\_\_\_

360

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR \_\_\_\_\_

Jerry's

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**