

Nº 11744

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11744

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

06/17/03

RECEIVED OF _____

FEE OF \$ _____

50

FOR WHICH PERMISSION IS GRANTED _____

H+W Contractors

REPAIR
TO TAP _____
CUTOFF

tap sanitary

SEWER ON THE _____

North

SI

OF _____

Walnut Road SE

AVE.

ST. TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

5171

, HOUSE NO. _____

1536

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

H+W

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**