Nº 11745

REMARKS ___

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 8-/5-03 HOUSE NO. 8285 SIZE OF PIPE USED 6" | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | 53′ |
|--|---|------------------------------|
| WAS LATERAL AT CURB? | | H+W |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR | 7. 100 |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU | JILDING SERVED. | 747 14th ST SE 45° -47' -22° |
| SIGNED Bill Pappas Inspector for City | FILED AT ENGINEE | ER'S OFFICE |

Nº 11745

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | MASSILLON, OHIO, $O6/17/O_25$ | | |
|--|-------------------------------|--|--|
| RECEIVED OF | FEE OF \$ | | |
| FOR WHICH PERMISSION IS GRANTED | W Contractors | | |
| | /ER ON THE | | |
| OF 1410 ST SE ST. TYL | PE OF STREET | | |
| THE PREMISES BEING LOT NO. \$285 | , HOUSE NO | | |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE. | | | |
| NAME OF CONTRACTOR ### | | | |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.