

Nº 11747

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/19/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 2812

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH ---


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Jerry's

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11747

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

06/18/03

RECEIVED OF _____

FEE OF \$ _____

5

FOR WHICH PERMISSION IS GRANTED _____

Jerry's Excavating

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE _____

North

SII

OF _____

Autumn Ave NW

AVE.
ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO. _____

16466

HOUSE NO. _____

2812

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Jerry's

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.