Nº 11762

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---|--|
| HOUSE NO. | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT |
| WAS LATERAL AT CURB? | CURB LINE AND DEPTH |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL | OF BUILDING SERVED. |
| | |
| | |
| | |
| | |
| | |
| | |
| | FILED AT ENGINEER'S OFFICE |
| SIGNEDInspector for City | |
| | |
| REMARKS | |

Nº 11762

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | MASSILLON, OHIO, | 6/3,00 | |
|--|-------------------------|-------------------------------|------|
| RECEIVED OF | | FEE OF \$ | 50 |
| REPAIR TO TAP SEWER | ON THE | East aghilt | SIDE |
| THE PREMISES BEING LOT NO | , HOUSE NO. | 2410 | |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.19 DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR | 71 DULY PASSED BY THE C | CITY COUNCIL, AND RULES OF TH | Ξ |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.