

Nº 11768

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/23/03

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 170'

HOUSE NO. 2911-2947

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Malovite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to Scale



SIGNED _____

J. Kelly m. Kelly

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11768

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

7/21, 20 3

RECEIVED OF _____

Malavite

FEE OF \$ _____

50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sewer

SEWER ON THE _____

South

SIDE

OF _____

Alexandria Blvd

AVE

TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

01523

, HOUSE NO. _____

2411-2447

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Malavite

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**